

Certificate of Analysis AIHA-LAP EMLAP# 102747

7184 North Park Drive Pennsauken, New Jersey 08109 (856) 486-1177

Date Collected: 09/27/2018
Date Received: 09/28/2018
Date Analyzed: 10/05/2018
Date Reported: 10/05/2018

Lab Sample #: 18037429-001

Project ID: 18037429 Page 1 of 2

www.aerobiology.net

Glen Rock, New Jersey 07452 Project: **#7129 - WOBOE - BUS GARAGE**

Condition of Sample(s) Upon Receipt: Acceptable

Client Sample #: BG-1-S-01

Garden State Envionmental

555 Broad Street Ste K

Sample Location: MENS RR (SINK)

Test: 1015.7, WATER, Legionella Analysis, CDC Method: SOP 2.35/SOP 2.22

- 1 LITER

Results: No Legionella isolated Liquid Volume: 1000 (mL)

MRL: 0.4 CFU/mL

Client Sample #: BG-1-S-02 Lab Sample #: 18037429-002

Sample Location: KITCHEN/BREAK ROOM (SINK)

Test: 1015.7, WATER, Legionella Analysis, CDC Method: SOP 2.35/SOP 2.22

- 1 LITER

Results: No Legionella isolated Liquid Volume: 1000 (mL)

MRL: 0.4 CFU/mL

Client Sample #: BG-1-HWH-01 Lab Sample #: 18037429-003

Sample Location: MAIN GARAGE (HOT WATER HEATER)

Test: 1015.7, WATER, Legionella Analysis, CDC Method: SOP 2.35/SOP 2.22

- 1 LITER

Results: No Legionella isolated Liquid Volume: 1000 (mL)

MRL: 0.4 CFU/mL

Client Sample #: BG-1-S-03 Lab Sample #: 18037429-004

Sample Location: SLOP SINK MAIN GARAGAE

Test: 1015.7, WATER, Legionella Analysis, CDC Method: SOP 2.35/SOP 2.22

- 1 LITER

Results: No Legionella isolated Liquid Volume: 1000 (mL)

MRL: 0.4 CFU/mL



Certificate of Analysis AIHA-LAP EMLAP# 102747

7184 North Park Drive Pennsauken, New Jersey 08109 (856) 486-1177 www.aerobiology.net

Date Collected: 09/27/2018
Garden State Envionmental
Date Received: 09/28/2018
Date Received: 09/28/2018
Date Received: 10/05/2018
Glen Rock, New Jersey 07452
Project: #7129 - WOBOE - BUS GARAGE
Date Reported: 10/05/2018
Project ID: 18037429

Condition of Sample(s) Upon Receipt: Acceptable Page 2 of 2

Legionella Facts

1. TESTING METHODOLOGY: Culture remains the recommended method for Legionella monitoring. Standardized culture procedures include ISO 11731: Detection and Enumeration of Legionella and CDC: Procedures for the Recovery of Legionella from the Environment.

Ref: BSR / ASHRE Standard 188P

- 2. Legionella species recovered from culture method include Legionella pneumophila and Legionella species not pneumophila. All Legionella pneumophila isolates are run against Serogroup 1 reagent and Serogroup 2-15 reagent. Legionella species not pneumophila isolates are screened in Legionella species reagent. (This species reagent includes micdadei, bozemanii, dumoffi, longbeachae, jordanis, gormanii, anisa and feelei)
- 3. If the final quantitative result is corrected for contamination based on the blank, the blank correction is stated in the sample comments section of the report.

Action Criteria for Legionella

| | | <u> </u> | |
|--------------------|---|---|-------------------|
| Legionella / ml | Cooling Towers and Evaporative Condensers | Suggested Remedial Action: Potable Water | Humidifier/Fogger |
| Detectable, but <1 | 1 | 2 | 3 |
| 1 - 9 | 2 | 3 | 4 |
| 10 - 99 | 3 | 4 | 5 |
| 100 - 999 | 4 | 5 | 5 |
| ≥ 1,000 | 5 | 5 | 5 |

Remedial Actions:

Level 1:

Review routine maintenance program recommended by the manufacturer of the equipment to ensure that the recommended program is being followed. The presence of barely detectable number of Legionella represents a low level of concern. Level 2:

Implement action 1. Conduct follow-up analysis after a few weeks for evidence of further Legionella amplification. This level of *Legionella* represents little concern, but the number of organisms detected indicates that the system is a potential amplifier of *Legionella*. Level 3:

Implement action 2. Conduct review of premises for the direct and indirect bioaerosols contact with occupants and health risk status of people who may come in contact with bioaerosols. Depending on the results of the review of the premises, action related to cleaning and/or biocide treatment of the equipment may be indicated. This level of *Legionella* represents a low but increased level of concern. I evel 4:

Implement action 3. Cleaning and/or biocide treatment of the equipment is indicated. This level of *Legionella* represents a moderately high level of concern, since it is approaching levels that may cause outbreaks. It is uncommon for samples to contain number of *Legionella* that fall in this category.

Level 5:

Immediate cleaning and/or biocide treatment of the equipment is definitely indicated. Conduct post treatment analysis to ensure effectiveness of the corrective action. The level of *Legionella* represents a high level of concern, since it poses the potential for causing an outbreak. It is very uncommon for samples to contain number of *Legionella* that fall in this category.

Ref: Legionella: Current Status and Emerging Perspectives: Barbaree, Breiman, Dufour: ASM



Suzanne S. Blevins, B.S., SM (ASCP)
Laboratory Director